

Applied Mechanics and Mechanics of Machinery Lab

Mechanical and Production Engineering Department

Ahsanullah University of Science & Technology (AUST)

General Lab Safety Rules

Wear PPE: Lab coat, safety goggles, gloves, and closed-toe shoes are mandatory.

No Unauthorized Entry: Only authorized students and staff are allowed in the lab.

Keep Workspace Clean: Ensure all equipment is stored properly and workspaces are clean after experiments.

No Eating or Drinking: Food and drinks are strictly prohibited to avoid contamination.

Safety Procedures for Specific Equipment

Epicyclic Gear Train: Secure setup and handle gears carefully to prevent dislodging.

Helical Spring Testing Apparatus: Align springs properly; avoid standing in front during tests.

Torsion Testing Machine: Fasten specimens securely before applying torque.

Combined Shear Force and Bending Moment Apparatus: Secure beams and avoid overloading the apparatus.

Accident and Health Hazard Provisions

First Aid Kit: Familiarize yourself with its location and basic first aid procedures.

Fire Safety: Know the emergency exits and fire alarm locations. Evacuate immediately if a fire cannot be controlled.

Incident Reporting: Report accidents immediately to the lab In-Charge. Investigations will be conducted to prevent future incidents

Lab Contact Information Lab In-Charge: Dr. Md. Kharshiduzzaman Emergency Contact: [LA:01743431974, AAO: 01534100141]

REMEMBER: Safety First! Always adhere to lab safety protocols.